## NOTICE TO MARINERS



## 103 (T) of 2024

Issued by Townsville Maritime Region on 5 March 2024

Area: Townsville pilotage area

Locality: Townsville, Cleveland Bay

Activity: Beacons established with temporary lights

Mariners are advised that:

The following beacons have been established and with temporary light characteristics.

|                                       | Latitude      | Longitude      | Temporary Light |
|---------------------------------------|---------------|----------------|-----------------|
| PDRL (Platypus Departure Rear Lead)   | 19° 10.4373'S | 146° 52.7267'E | Fl Y 2.5s       |
| PDFL (Platypus Departure Front Lead)  | 19° 11.1294'S | 146° 52.2771'E | FI R 4.3s       |
| SAFL (Sea channel Arrival Front Lead) | 19° 11.7252'S | 146° 51.9671'E | FIR 4.3s        |
| SARL (Sea channel Arrival Rear Lead)  | 19° 12.7140'S | 146° 51.5576'E | Fl Y 2.5s       |
| PAFL (Sea Channel Arrival Front Lead) | 19° 14.8449'S | 146° 51.8627'E | Fl Y 2.5s       |

These leads have been installed in preparation and will indicate the centre line of the widened channel once completed and declared. A further notice to mariners will be issued when the main lead lights have been installed and commissioned.

Mariners are advised to navigate with caution.

**Refer to notice:** 077(t) 2024, 049(t) 2024 **Cancel notice:** 077(t) 2024, 049(t) 2024

AUS charts affected: AUS256 ENC Cells affected: AU6TSV01, AU6TSV02, AU6TSV03, AU6TSV04; AU5TSV01

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office:

Phone 07 4421 8100 Email: vtstownsville@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Townsville) - Maritime Safety Queensland