## Department of Transport and Main Roads - Maritime Safety Queensland

## NOTICE TO MARINERS



## 222 of 2025

Issued by Brisbane Maritime Region on 30 May 2025

**Area:** Southport pilotage area

Locality: Logan River

**Activity:** aids to navigation altered and established

Mariners are advised that:

An unlit starboard beacon in approximate position latitude 27°42.654'S, longitude 153°18.595'E has been permanently replaced with an unlit starboard lateral buoy and has been altered in position to approximate position latitude 27°42.678'S, longitude 153°18.604'E.

An unlit starboard beacon in approximate position latitude 27°42.689'S, longitude 153°18.285'E has been permanently replaced with an unlit starboard lateral buoy.

An unlit port beacon in approximate position latitude 27°42.327′S, longitude 153°18.896′E has been permanently replaced with an unlit port lateral buoy.

An unlit port lateral buoy has been established in approximate position latitude 27°42.633′S, longitude 153°18.685′F.

An unlit starboard lateral buoy has been established in approximate position latitude 27°42.617'S, longitude 153°18.665'E.

Mariners should navigate with caution when transiting the area.

Refer to notice: Cancel notice:

AUS charts affected: AUS814 ENC Cells affected: AU428153

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Brisbane Regional Harbour Master's office:

Phone: 07 3632 7500 Email: vtsbrisbane@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Brisbane) - Maritime Safety Queensland