

NOTICE TO MARINERS

201 (T) of 2025

Issued by Cairns Maritime Region on 20 May 2025

Area: Skardon River pilotage area
Locality: Skardon River entrance channel
Activity: Navigation aids

Mariners are advised that:

The navigation aids below define the entrance channel to Skardon River, positions are approximate;

NAME	TYPE	LIGHTING	LATITUDE	LONGITUDE
SB- Safe Water Bouy (RW)	Buoy	Fl.W.3s	11° 46.043'S	141° 57.106'E
S1- Stbd Lateral Mark	Buoy	Fl.G.5s	11° 46.188'S	141° 57.512'E
P2-Port Lateral Mark	Buoy	Fl.R.5s	11° 46.149'S	141° 57.537'E
S3- Stbd Lateral Mark	Buoy	Fl.G.5s	11° 46.274'S	141° 57.647'E
P4-Port Lateral Mark	Buoy	Fl.R.5s	11° 46.287'S	141° 57.738'E
S5- Stbd Lateral Mark	Buoy	Fl.G.5s	11° 46.359'S	141° 57.756'E
P6-Port Lateral Mark	Buoy	Fl.R.5s	11° 46.306'S	141° 57.848'E
S7- Stbd Lateral Mark	Buoy	Fl.G.5s	11° 46.353'S	141° 57.932'E
P8-Port Lateral Mark	Buoy	Fl.R.5s	11° 46.252'S	141° 58.100'E
S9- Stbd Lateral Mark	Buoy	Fl.G.5s	11° 46.320'S	141° 58.110'E
P10-Port Lateral Mark	Buoy	Fl.R.5s	11° 46.237'S	141° 58.360'E
S11- Stbd Lateral Mark	Buoy	Fl.G.5s	11° 46.273'S	141° 58.374'E
P12-Port Lateral Mark	Buoy	Fl.R.5s	11° 46.168'S	141° 58.466'E
S13- Stbd Lateral Mark	Buoy	Fl.G.5s	11° 46.197'S	141° 58.491'E
P14-Port Lateral Mark	Buoy	Fl.R.5s	11° 46.031'S	141° 58.586'E
S15- Stbd Lateral Mark	Buoy	Fl.G.5s	11° 46.067'S	141° 58.616'E
P16-Port Lateral Mark	Buoy	Fl.R.5s	11° 45.542'S	141° 59.367'E
TSB- Tide Station Beacon	Beacon	Fl.Y.4s	11° 45.452'S	141° 59.575'E
S17 – Stbd Lateral Mark	Buoy	Fl.G.5s	11° 45.540'S	141° 59.687'E
P18-Port Lateral Mark	Buoy	Fl.R.5s	11° 45.436'S	141° 59.796'E
P20-Port Lateral Mark	Buoy	Fl.R.5s	11° 45.383'S	142° 00.396'E
SR1- Isolated Danger Mark	Buoy	Fl.W.(2)10s	11° 45.424'S	142° 00.809'E
S19-Stbd Lateral Mark	Buoy	Fl.G.5s	11° 45.503'S	142° 01.070'E
SLB1- Sector Light Beacon	Beacon	SectRWG	11° 45.513'S	142° 01.280'E
P22-Port Lateral Mark	Buoy	Fl.R.5s	11° 45.378'S	142° 01.439'E
S21-Stbd Lateral Mark	Buoy	Fl.G.5s	11° 44.898'S	142° 02.535'E
SLB2/3- Sector Light Beacon	Beacon	SectRWG	11° 44.470'S	142° 03.260'E
S23-Stbd Lateral Mark	Buoy	Fl.G.5s	11° 44.642'S	142° 03.350'E
SLB4- Sector Light Beacon	Beacon	SectRWG	11° 44.803'S	142° 04.175'E
S25-Stbd Lateral Mark	Buoy	Fl.G.5s	11° 45.009'S	142° 04.217'E

P24-Port Lateral Mark	Buoy	Fl.R.5s	11° 45.226'S	142° 04.362'E
SR2 - Isolated Danger Mark	Buoy	Fl.W.(2)10s	11° 45.461'S	142° 04.432'E
SLB5- Sector Light Beacon	Beacon	SectRWG	11° 45.583'S	142° 04.423'E

Refer to notice: 185(T) of 2025
 Cancel notice: 185(T) of 2025

AUS charts affected: AUS 301, 4060 and 4603
 ENC Cells affected: AU412141, AU412142, AU130120, AU220140

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Cairns Regional Harbour Master’s office:

Phone 07 4052 7400

Email: vtscairns@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Cairns) - Maritime Safety Queensland