

NOTICE TO MARINERS



064 of 2024

Issued by Townsville Maritime Region on 9 February 2024

Area: North Queensland
Locality: Enterprise Channel, Dungeness, Lucinda
Activity: Buoyage altered.

Mariners are advised that:

Due to the changing profile of Enterprise Channel and recent siltation the buoyage has been altered as follows,

	Latitude	Longitude	Light	Top mark	Remark
No 1 (Special Mark)	18° 30.933'S	146°19.281'E	Fl Y 2s	No top mark	Repositioned
No 2 (Special Mark)	18° 31.170'S	146°19.042'E	Fl Y 2.5	No top mark	New

The following Port Lateral marks have been permanently withdrawn.

	Approximate Position		Remark
	Latitude	Longitude	
Port Lateral No 6	18° 31.014'S	146°19.200'E	Permanently withdrawn
Port Lateral No 8	18° 31.037'S	146°19.157'E	Permanently withdrawn
Port Lateral No 10	18° 31.136'S	146°19.080'E	Permanently withdrawn

A clear channel cannot be defined between Special mark buoy No1 and Special mark buoy No2. Mariners are advised the seabed between Special mark buoy No1 and Special mark buoy No2 is considered mobile sea floor, is subjected to shoaling and depths will vary over time.

Mariners are advised to navigate with extreme caution when crossing the sand bars between Special mark buoy No1 and Special mark buoy No2.

Refer to notice: none

Cancel notice: None

AUS charts affected: AUS259, AUS267

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office:

Phone 07 4421 8100

Email: vtstownsville@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Townsville) - Maritime Safety Queensland