



ADVICE

Issued by Cairns Maritime Region on 18 November 2024

Area: Cooktown pilotage area
Locality: Cooktown Harbour entrance channel
Activity: Navigation buoy reported as out of position.

Mariners are advised that:

Endeavour River #6/Port hand buoy #6 has been reported as out of position (as at 14th November 2024).

Light characteristics remain unchanged (FL(R) 2.5s). No current GPS position has been reported.

Mariners are to navigate with caution.

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Cairns Regional Harbour Master's office:

Phone 07 4052 7400

Email: vtscairns@msq.qld.gov.au

Notice authorised by: **Regional Harbour Master (Cairns) - Maritime Safety Queensland**