NOTICE TO MARINERS



518 of 2023

Issued by Townsville Maritime Region on 17 November 2023

- Area: Townsville pilotage area
- Locality: Townsville, Cleveland Bay
- Activity: Special mark buoy established

Mariners are advised that:

A special mark buoy TYC No 2 Fl.Y 2.5s has been established in approximate position Latitude 19° 13.840'S Longitude 146° 55.900'E. The buoy is not fitted with a topmark. The buoy is used as a turning mark for yacht races.

Mariners are advised to navigate with caution in the area.

Refer to notice: none Cancel notice: none

AUS charts affected: AUS256, AUS257

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office:

Phone 07 4421 8100

Email: vtstownsville@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Townsville) - Maritime Safety Queensland