

NOTICE TO MARINERS

170 of 2025

Issued by Cairns Maritime Region on 29 April 2025

Area: Far North Queensland
Locality: Saibai Island – Torres Straits
Activity: Aid to navigation established in position

Mariners are advised that:

A port lateral marker buoy displaying light characteristics FL R 2.5s has been established mid-way along the approach channel into Saibai Island in approximate position, latitude 09°22.623'S, longitude 142° 36.722'E.

Location and light characteristics of previously established aid to navigation buoys to mark the approach channel into Saibai Island are below.

Aid to Navigation	Latitude	Longitude	Light Characteristics
Saibai Island #1	09° 22.451'S	142° 36.585'E	Fl G 2.5s
Saibai Island #2	09° 22.400'S	142° 36.646'E	FL R 2.5s
Saibai Island #3	09° 22.755'S	142° 36.742'E	Fl G 2.5s
Saibai Island #4	09° 22.623'S	142° 36.722'E	FL R 2.5s
Saibai Island #6	09° 22.748'S	142° 36.814'E	FL R 2.5s

Mariners are to navigate with caution.

Refer to notice: none

Cancel notice: none

AUS charts affected: AUS 841

ENC Cells affected: none

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Cairns Regional Harbour Master's office:

Phone 07 4052 7400

Email: vtscairns@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Cairns) - Maritime Safety Queensland