



# NOTICE TO MARINERS

## 593 of 2023

---

Issued by Cairns Maritime Region on 5 December 2023

**Area:** Far North Queensland  
**Locality:** Boigu Island East  
**Activity:** Port Lateral mark established

Mariners are advised that:

A port lateral marker buoy has been established mid-way along the approach channel. A red port lateral marker buoy, light characteristics Fl R 2.5s has been established in approximate position Latitude: 09° 13.61' S, Longitude 142° 13.30' E.

Mariners are to navigate with caution.

**Refer to notice:** 576 of 2023

**Cancel notice:** 576 of 2023

**AUS charts affected:** AUS 841

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

**For further information about this notice, please contact:**

The Cairns Regional Harbour Master's office:

Phone 07 4052 7400

Email: [vtscairns@msq.qld.gov.au](mailto:vtscairns@msq.qld.gov.au)

**Notice authorised by:** Regional Harbour Master (Cairns) - Maritime Safety Queensland