

NOTICE TO MARINERS

541 of 2023

Issued by Mackay Maritime Region on 24 November 2023

Area: Mackay pilotage area
Locality: Mackay Harbour
Activity: Port Entry Light and Rear Leading Light established

Mariners are advised that:

A Port entry sector light with centreline bearing 254.8° (T) has been installed in the following position:

Latitude 21° 06.4173' S, longitude 149° 13.6295' E.

The centre sector displays a white light with a 2' arc.
The northern 2 sectors are each 2' arc and display green flashing lights.
The southern 2 sectors are each 2' arc and display red flashing lights.

A Rear Lead light has been established with a centreline bearing 254.8° T in the following position.

Latitude 21° 06.4885' S, longitude 149° 13.3497' E.

The light characteristics are as follows F.Bu.38.5m 2M and marks the centre of the channel into Mackay Harbour.

Both of these lights have been aligned and commissioned and can be safely used for navigation.

Refer to notice: none
Cancel notice: 448 of 2023

AUS charts affected: 249,250

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Mackay Regional Harbour Master's office:

Phone 07 4944 3700

Email: vtshaypoint@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Mackay) - Maritime Safety Queensland