

NOTICE TO MARINERS

415 of 2023

Issued by Mackay Maritime Region on 15 September 2023

Area: Mackay pilotage area
Locality: Mackay Marina NIB wall
Activity: Port lateral beacon established

Mariners are advised that:

Port Lateral beacon Fl.(R) 2.5s has been established in position 21° 06.646 'S, 149° 13.722 'E.

The beacon is located on the end of the newly constructed Nib Wall at the entrance to Mackay Marina.

All mariners are advised to navigate with caution transiting the area.

Refer to notice: none

Cancel notice: none

AUS charts affected: 250, 823

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Mackay Regional Harbour Master's office:

Phone 07 4944 3700

Email: vtshaypoint@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Mackay) - Maritime Safety Queensland