

NOTICE TO MARINERS

535 (T) of 2023

Issued by Gladstone Maritime Region on 21 November 2023

Area: Maryborough pilotage area

Locality: Urangan Boat Harbour

Activity: Boat harbour depths

Mariners are advised that:

The depths at the entrance and within Urangan Boat Harbour are less than charted due to siltation.

A survey in August 2021, revealed a minimum depth of 2.0 metres below Lowest Astronomical Tide within the boat harbour entrance channel. Depths less than charted also exist within the boat harbour.

Mariners are to proceed with caution when approaching and within the boat harbour and should seek advice from the Boat Harbour Controller or the local Volunteer Marine Rescue if unsure of current conditions.

Refer to notice: none

Cancel notice: 322 (T) of 2021

AUS charts affected: AUS817

ENC Cells affected: AU426152,

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Gladstone Regional Harbour Master's office:

Phone 07 4839 0208

Email: vtsgladstone@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Gladstone) - Maritime Safety Queensland