

NOTICE TO MARINERS



088 (T) of 2024

Issued by Cairns Maritime Region on 27 February 2024

Area: Cooktown pilotage area
Locality: Endeavour River
Activity: Establishment and replacement of navigation aids

Mariners are advised that:

the following aids to navigation located in the Endeavour River, Cooktown have been **altered** in approximate position.

Aid to Navigation	Latitude	Longitude	Colour	Light Characteristic
Endeavour River No.1	15° 27.204'S	145° 15.328'E	Green	Fl G 2.5s
Endeavour River No.2	15° 27.224'S	145° 15.361'E	Red	Fl R 2.5s
Endeavour River No.3	15° 27.309'S	145° 15.194'E	Green	Fl G 2.5s
Endeavour River No.4	15° 27.352'S	145° 15.220'E	Red	Fl R 2.5s
Endeavour River No.5	15° 27.417'S	145° 15.064'E	Green	Fl G 2.5s
Endeavour River No.6	15° 27.455'S	145° 15.098'E	Red	Fl R 2.5s
Endeavour River No.7	15° 27.456'S	145° 15.020'E	Yellow	Fl Y 3s
Endeavour River No.9	15° 27.520'S	145° 14.971'E	Yellow	Fl Y 3s

Mariners are advised the following aids to navigation located in the Endeavour River, Cooktown have been **established** in approximate position.

Aid to Navigation	Latitude	Longitude	Colour	Light Characteristic
Endeavour River No.11	15° 27.594'S	145° 14.936'E	Yellow	Fl Y 3s
Endeavour River No.13	15° 27.696'S	145° 14.918'E	Yellow	Fl Y 3s

Aids to navigation buoys No.1 to No.6 mark the entrance channel to the Endeavour River, Cooktown.

Aids to navigation buoys No.7 to No.13 mark the swing basins in front of the Cooktown fuel wharves and public boat ramp infrastructure. Apart from approved buoy moorings, vessels are not to anchor inside this area to ensure ship operations are not impeded.

Mariners are to navigate with caution.

Refer to notice: none

Cancel notice: none

AUS charts affected: AUS831

ENC Cells affected: AU5CTN01

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Cairns Regional Harbour Master's office:

Phone 07 4052 7400

Email: vtscairns@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Cairns) - Maritime Safety Queensland