

NOTICE TO MARINERS



283 of 2025

Issued by Brisbane Maritime Region on 26 June 2025

Area: Brisbane pilotage area
Locality: Erapah Creek, Southern Moreton Bay
Activity: Aid to Navigations - Altered

Mariners are advised that:

Erapah Creek 3, an unlit Starboard lateral beacon in approximate position latitude 27°33.795'S, longitude 153°17.771'E has been altered to Erapah Creek 5.

Erapah Creek 5, an unlit Starboard lateral beacon in approximate position latitude 27°33.845'S, longitude 153°17.408'E has been altered to Erapah Creek 9.

Erapah Creek 9, an unlit Starboard lateral beacon in approximate position latitude 27°33.521'S, longitude 153°17.977'E has been altered to Erapah Creek 3.

Erapah Creek 12, an unlit Port lateral beacon in approximate position latitude 27°33.480'S, longitude 153°17.942'E has been altered to Erapah Creek 10.

Erapah Creek 14, an unlit Port lateral beacon in approximate position latitude 27°33.470'S, longitude 153°17.895'E has been altered to Erapah Creek 12.

Erapah Creek 16, an unlit Port lateral beacon in approximate position latitude 27°33.471'S, longitude 153°17.866'E has been altered to Erapah Creek 14.

Erapah Creek 18, an unlit Port lateral beacon in approximate position latitude 27°33.500'S, longitude 153°17.765'E has been altered to Erapah Creek 16.

Erapah Creek 20, an unlit Port lateral beacon in approximate position latitude 27°33.530'S, longitude 153°17.742'E has been altered to Erapah Creek 18.

Erapah Creek 22, an unlit Port lateral beacon in approximate position latitude 27°33.713'S, longitude 153°17.628'E has been altered to Erapah Creek 20.

Erapah Creek 24, an unlit Port lateral beacon in approximate position latitude 27°33.720'S, longitude 153°17.633'E has been altered to Erapah Creek 22.

Erapah Creek 26, an unlit Port lateral beacon in approximate position latitude 27°33.760'S, longitude 153°17.578'E has been altered to Erapah Creek 24.

Erapah Creek 28, an unlit Port lateral beacon in approximate position latitude 27°33.785'S, longitude 153°17.505'E has been altered to Erapah Creek 26.

Eprapah Creek 30, an unlit Port lateral beacon in approximate position latitude 27°34.090'S, longitude 153°17.370'E has been altered to Eprapah Creek 28.

Eprapah Creek 32, an unlit Port lateral beacon in approximate position latitude 27°34.138'S, longitude 153°17.355'E has been altered to Eprapah Creek 30.

Mariners are advised to navigate with caution in the area.

Refer to notice: none

Cancel notice: none

AUS charts affected: AUS814

ENC Cells affected: AU428153

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Brisbane Regional Harbour Master's office:

Phone: 07 3632 7500

Email: vtsbrisbane@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Brisbane) - Maritime Safety Queensland