

# NOTICE TO MARINERS

## 123 of 2023

---

Issued by Townsville Maritime Region on 20 March 2023

**Area:** Abbot Point pilotage area  
**Locality:** Port Denison  
**Activity:** Small vessel mooring area, special mark buoys established

Mariners are advised that:

A small vessel mooring area has been established in Port Denison bounded by the following coordinates.

|              | Latitude       | Longitude      |           |                   |
|--------------|----------------|----------------|-----------|-------------------|
| North Corner | 20° 01.3087 'S | 148° 15.5942'E |           |                   |
| NE Corner    | 20° 01.5112'S  | 148° 15.8607'E |           |                   |
| PBMG No 1    | 20° 01.6470'S  | 148° 15.7550'E | Fl Y 2.5s | Special mark buoy |
| PBMG No 2    | 20° 01.4340'S  | 148° 15.4970'E | Fl Y 2.5s | Special mark buoy |

Two special buoys have been established on the Southern points of the buoy mooring grid. Mariners are advised unlit mooring buoys exist within the mooring area and vessels should avoid transiting through the area.

Mariners are advised to navigate with caution.

**Refer to notice:** none

**Cancel notice:** none

**AUS charts affected:** 268, 825, 826

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA94 datum.

**For further information about this notice, please contact:**

The Townsville Regional Harbour Master's office:

Phone 07 4421 8100

Email: vtstownsville@msq.qld.gov.au

**Notice authorised by:** Regional Harbour Master (Townsville) - Maritime Safety Queensland