

NOTICE TO MARINERS

208 (T) of 2025

Issued by Townsville Maritime Region on 22 May 2025

Area: North Queensland
Locality: Missionary Bay, Hinchinbrook Island
Activity: Special mark buoy – reported missing

Mariners are advised that:

The special mark buoy "No.5" FL Y.4s in approximate position latitude 18°12.341'S longitude 146°09.355'E located in Missionary Bay has been reported missing.

Mariners are advised to navigate with caution.

Refer to notice: none

Cancel notice: none

AUS charts affected: AUS828

ENC Cells affected: AU419146

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office:

Phone 07 4421 8100

Email: vtstownsville@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Townsville) - Maritime Safety Queensland