

# NOTICE TO MARINERS



## 617 (T) of 2023

---

Issued by Cairns Maritime Region on 21 December 2023

**Area:** Far North Queensland  
**Locality:** Daintree River  
**Activity:** Temporary Removal of Aids to Navigation

Mariners are advised that:

Daintree River # 1 lateral buoy in approximate position latitude 16°18.602'S, longitude 145°26.827'E has been temporarily removed.

Daintree River #2 lateral buoy in approximate position latitude 16°17.956'S, longitude 145°26.937'E has been temporarily removed.

Mariners are to navigate with caution as the entrance to the Daintree River may have been altered during severe weather received in December 2023.

**Refer to notice:** none

**Cancel notice:** none

**AUS charts affected:** 831

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

**For further information about this notice, please contact:**

The Cairns Regional Harbour Master's office:

Phone 07 4052 7400

Email: [vtscairns@msq.qld.gov.au](mailto:vtscairns@msq.qld.gov.au)

**Notice authorised by:** Regional Harbour Master (Cairns) - Maritime Safety Queensland