

NOTICE TO MARINERS

228 of 2024

Issued by Cairns Maritime Region on 10 May 2024

Area: Far North Queensland
Locality: Torres Strait
Activity: Newly installed beacons

Mariners are advised that:

The following permanent beacons have been installed

Warraber

NAME	LIGHTING	LATITUDE	LONGITUDE
No. 1 – Stbd Lateral Mark	Fl (5s) G	10° 12.212' S	142° 49.318' E.
No. 4 - Port Lateral Mark	Fl (5s) R	10° 12.137' S	142° 49.303" E.
No. 6 - Port Lateral Mark	Fl (5s) R	10° 12.235" S	142° 49.381' E.

Mabuiag

NAME	LIGHTING	LATITUDE	LONGITUDE
No. 1 – Stbd Lateral Mark	Fl (5s) G	09° 57.061' S	142° 12.081' E.
No. 2 - Port Lateral Mark	Fl (5s) R	09° 57.091' S	142° 12.077' E.

Turnagain Island

NAME	LIGHTING	LATITUDE	LONGITUDE
Turnagain Island	Fl (5s) Y	09° 32.945' S	142° 13.799' E.
Nurmar Reef	Fl (5s) Y	09° 40.941' S	142° 22.366' E.

Refer to notice: none

Cancel notice: none

AUS charts affected: AUS 839, 841

ENC Cells affected: AU411142, AU410142, PG410142

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Cairns Regional Harbour Master's office:

Phone 07 4052 7400

Email: vtscairns@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Cairns) - Maritime Safety Queensland