

# NOTICE TO MARINERS

## 027 (T) of 2023

---

Issued by Mackay Maritime Region on 15 January 2024

**Area:** Mackay pilotage area

**Locality:** Pioneer River

**Activity:** Navigational Hazard

Mariners are advised that:

A yacht has sunk approximately 500m downstream from the River St boat ramp in the Pioneer River Mackay. The mast is visible at high tide.

A special mark buoy with light characteristics Fl(Y) 2.5s has been established in approximate position 21°08.473' S, 149°12.174 ' E which indicates a navigational hazard below the surface.

All mariners are advised to navigate with caution.

**Refer to notice:** none

**Cancel notice:** none

**AUS charts affected:** 250,823

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

**For further information about this notice, please contact:**

The Mackay Regional Harbour Master's office:

Phone 07 4944 3700

Email: vtshaypoint@msq.qld.gov.au

**Notice authorised by:** Regional Harbour Master (Mackay) - Maritime Safety Queensland