## Department of Transport and Main Roads - Maritime Safety Queensland

## NOTICE TO MARINERS



## 157 of 2023

Issued by Gladstone Maritime Region on 6 April 2023

Area: Capricorn Coast

**Locality:** Elliott River

Activity: Repositioned Aids to Navigation, changes to existing aid to navigation characteristics and

the withdrawal of a starboard lateral beacon.

Mariners are advised that:

Maritime Safety Queensland has removed and repositioned a number of aids to navigation in the Elliott River.

Aids to navigation in the river are not lit and the new approximate positions are as follows:

Elliott River 2 Red buoy repositioned to – Latitude 24° 55.680' S longitude 152° 29.451'E

**Elliott River 1** Existing starboard lateral beacon removed, and a green buoy established in new position – latitude 24° 55.787'S longitude 152° 29.118'E

Elliott River 3 Starboard lateral beacon removed as no longer required

Elliott River 4 (red buoy) and Elliott River 6 (port lateral beacon)

Remain in existing charted positions

Sand shoaling in Elliott River is rapidly changing and mariners are advised to navigate the area with caution and seek local knowledge before crossing the bar.

Refer to notice: none Cancel notice: none

AUS charts affected: AUS817 ENC Cells affected: AU425152

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA94 datum.

For further information about this notice, please contact:

The Gladstone Regional Harbour Master's office:

Phone 07 4971 5200 Email: vtsgladstone@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Gladstone) - Maritime Safety Queensland