

# NOTICE TO MARINERS

## 317 (T) of 2025

---

Issued by Gladstone Maritime Region on 11 July 2025

**Area:** Maryborough pilotage area  
**Locality:** Mary River, Maryborough  
**Activity:** M16 port lateral marker out of charted position

Mariners are advised that:

Mary River, Maryborough port lateral marker M16 has been reported out of charted position by approximately 150 – 200 metres.

Mariners are advised to transit the area with caution.

**Refer to notice:** none

**Cancel notice:** none

**AUS charts affected:** AUS817

**ENC Cells affected:** AU426152

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

**For further information about this notice, please contact:**

The Gladstone Regional Harbour Master's office:

Phone 07 4839 0208

Email: [vtsgladstone@msq.qld.gov.au](mailto:vtsgladstone@msq.qld.gov.au)

**Notice authorised by:** Regional Harbour Master (Gladstone) - Maritime Safety Queensland