Department of Transport and Main Roads - Maritime Safety Queensland

NOTICE TO MARINERS



095 (T) of 2025

Issued by Gladstone Maritime Region on 17 March 2025

Area: Maryborough pilotage area

Locality: Tin Can Bay Inlet

Activity: Characteristics of aids to navigation

Mariners are advised that:

The characteristics of the following aids to navigation in the Tin Can Bay Inlet have been altered and are synchronised as follows.

NAME POSITION CHARACTERISTIC

Carlo front North lead $25^{\circ} 52.7352' \text{ S } 153^{\circ} 02.6389' \text{E}$ Fl W Q (0.3 on + 0.7 off) Carlo front West lead $25^{\circ} 53.4649' \text{ S } 153^{\circ} 02.5072' \text{E}$ Fl W Q (0.3 on + 0.7 off)

Refer to notice: none

Cancel notice: 587(T) of 2023

AUS charts affected: AUS815, AUS 817

ENC Cells affected: AU42153

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Gladstone Regional Harbour Master's office:

Phone 07 4839 0208 Email: vtsgladstone@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Gladstone) - Maritime Safety Queensland