



NOTICE TO MARINERS

540 (T) of 2023

Issued by Gladstone Maritime Region on 24 November 2023

Area: Maryborough pilotage area
Locality: Tin Can Bay Inlet
Activity: Characteristics of aids to navigation

Mariners are advised that:

The characteristics of the following aids to navigation in the Tin Can Bay Inlet have been altered and are synchronised as follows.

NAME	POSITION	CHARACTERISTIC
Carlo front North lead	25° 52.7352' S 153° 02.6389'E	Fl W 3s (0.3 on + 2.7 off)
Carlo front West lead	25° 53.4649' S 153° 02.5072'E	Fl W 3s (0.3 on + 2.7 off)
Teebar Creek 2 special mark	25° 51.5497' S 153° 02.1689'E	Fl Y 3s (0.3 on + 2.7 off)

Refer to notice: none
Cancel notice: none

AUS charts affected: AUS815, 817
ENC Cells affected: AU426153

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Gladstone Regional Harbour Master's office:
Phone 07 4839 0208 Email: vtsgladstone@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Gladstone) - Maritime Safety Queensland