## NOTICE TO MARINERS



## 158 (T) of 2025

Issued by Gladstone Maritime Region on 23 April 2025

Area: Maryborough pilotage area

Locality: Burrum River mouth

Activity: Navigation hazard in Burrum River mouth

Mariners are advised that:

A hazard to navigation has been reported in the mouth of the Burrum River in the vicinity of the port lateral beacon at approximate latitude 25°10.249'S, longitude 152°38.948'E.

The hazard is described as a semi-submerged solid object fixed to the seabed, which slightly protrudes from the water line at undefined tidal ranges.

Mariners should navigate with caution when transiting this area.

Refer to notice: none Cancel notice: none

AUS charts affected: 242, 817 ENC Cells affected: AU425152

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Gladstone Regional Harbour Master's office:

Phone 07 4839 0208

Email: vtsgladstone@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Gladstone) - Maritime Safety Queensland