## NOTICE TO

## MARINERS



## 318 of 2025

Issued by Mackay Maritime Region on 11 July 2025

Area: Whitsundays pilotage area

Locality: Hamilton Island airport runway

Activity: Flight path caution to vessels

Mariners are advised that:

Vessels operating in Dent Passage between Titan Island and the Hamilton Island airstrip are advised that there are frequent aircraft movements in this area 24 hours a day, seven days a week. Vessels with an overall height greater than eight metres are advised to keep clear of the flight path zone during aircraft movements. These vessels if entering Hamilton Island marina are advised to keep to the eastern side of Dent passage and are not to stop in the aircraft zone (refer attached chartlet). This restriction also applies to the southern end of the runway in Driftwood Bay.

Mariners should navigate with caution in the area.

Refer to notice: none Cancel notice: none

AUS charts affected: 252, 253 ENC Cells affected: AU5HTI01

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Mackay Regional Harbour Master's office:

Phone 07 4944 3700 Email

. 3700 Email: vtshaypoint@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Mackay) - Maritime Safety Queensland

## **NOTICE TO MARINERS**

**BE AWARE OF AIRCRAFT MOVEMENTS AT HAMILTON ISLAND** 

FOR SAFETY REASONS, ALL VESSELS MUST REMAIN CLEAR OF THE AIRCRAFT APPROACH/ DEPARTURE PATH. ENSURE YOUR VESSEL'S MAST HEIGHT DOES NOT INFRINGE UPON AIRCRAFT OBSTACLE CLEARANCE ZONES.

