## Department of Transport and Main Roads - Maritime Safety Queensland

## NOTICE TO MARINERS



## 411 of 2023

Locality:

Issued by Townsville Maritime Region on 12 September 2023

Area: Lucinda pilotage area

Activity: Special Mark established

Dungeness, Lucinda

Mariners are advised that:

Dungeness Fairway Special Mark buoy Fl Y 2s has been established in position Latitude 18° 31.002'S, 146° 19.280'E. The buoy marks the entrance to Dungeness Channel.

Mariners are advised to navigate with caution.

Refer to notice: none

Cancel notice: 225 (T) 2021

AUS charts affected: 267, 259, 828

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

For further information about this notice, please contact:

The Townsville Regional Harbour Master's office:

Phone 07 4421 8100 Email: vtstownsville@msq.qld.gov.au

Notice authorised by: Regional Harbour Master (Townsville) - Maritime Safety Queensland