

# NOTICE TO MARINERS



## 605 (T) of 2023

---

Issued by Cairns Maritime Region on 17 December 2023

**Area:** Port Douglas pilotage area  
**Locality:** Dickson Inlet channel  
**Activity:** Seaward channel buoys reported as off station

Mariners are advised that:

The seaward channel buoys have been reported as being off station to the North West of their charted position by approximately 100 meters.

Mariners are advised to navigate with caution.

**Refer to notice:** none

**Cancel notice:** none

**AUS charts affected:** 270, 830

---

Latitude and longitude positions are on WGS84 horizontal datum and are compatible with GDA2020 datum.

**For further information about this notice, please contact:**

The Cairns Regional Harbour Master's office:

Phone 07 4052 7400

Email: [vtscairns@msq.qld.gov.au](mailto:vtscairns@msq.qld.gov.au)

**Notice authorised by:** Regional Harbour Master (Cairns) - Maritime Safety Queensland